

- High sensitivity, miniature AC/DC clamp meter.
- 0.1mA minimum resolution for AC current and 1mA minimum resolution for DC current.
- Output terminal for recorder connection.

Φ 7.5 MAX AC/DC20A OUT PUT

External Power Supply



| | |
|--------------------|--|
| AC A | 200mA/2/20A ±1%rdg±2dgt [50/60Hz] (200mA) ±1.5%rdg±4dgt [40Hz~2kHz] (200mA) ±1%rdg±2dgt [50/60Hz] (2A) ±2.5%rdg±5dgt [40Hz~2kHz] (2/20A) |
| DC A | 2/20A ±1%rdg±2dgt (2A) ±1.5%rdg±4dgt (20A) |
| Output Voltage | 200mV DC for 200mA AC/DC and 2A/20A AC/DC full scale |
| Conductor Size | Ø7.5mm max. |
| Frequency Response | DC, 40Hz~2kHz |
| Withstand Voltage | 750V AC for 1 minute |
| Power Source | 6LF22(9V) × 1 or AC Adaptor |
| Dimensions | 142(L) × 64(W) × 26(D)mm 153(L) × 23(W) × 18(D)mm Clamp Sensor |
| Weight | 220g approx. |
| Accessories | 9071(Carrying Case) Alkaline 6LF22 × 1 Instruction Manual |
| Optional | 8022 (AC Adaptor)(110V) 8023 (AC Adaptor)(220V) 7014 (Output Cord) |